



*Figure 8. "One-site-itis" due to repeated needle puncture in the same location the result of poor needle site rotation.*